





## Paintmask PPM Flex 3.0




PPM Flex 2.0 is especially designed for masking wet paints, but in some cases it can be used also for powder coatings. Depending of the painted surfaces the mask can be heated up till 200°C.




The surface to be masked, should be clean and free from dust.




Peel the mask from the paper liner and apply it on the surface which must be covered. Be sure that especially the edges are applied without any air bubbles or tearings.



Spray the surface with a wet paint or powder coating.



Cure the surface with the mask on it, at the temperature which is needed to cure the paint correctly.



After curing peel of the mask. In some cases it's more suitable to do this when both, surface and mask are still warm.



PPM Flex 3.0 has a long shelf life. The duration of it depends of the conditions of your warehouse. Stored flat in the original packaging by room temperature with a humidity of approximately 50% will give the best results.